

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

August 18, 2009

Reviewed:	LK.

Mine Name: Tony M	Permit number: M/017/0049
Operator Name: Denison Mines	Inspection Date May 6, 2009
	Time: 11:00 AM 1:00 PM

Inspector(s): Wayne Western

Other Participants: Darryl Winters Permittee, Buzz Rakow BLM

Mine Status: Active Weather: Clear, 80s

Elements of Inspection	Evaluated	Comment	Enforcement
 Permits, Revisions, Transfer, Bonds, Permit Fees Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control, safety) Concurrent Reclamation Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) 			
8. Soils9. Revegetation10. Other			

Purpose of Inspection:

The main purpose of the inspection was to determine the status of the mine and for the inspector to become familiar with the site.

Inspection Summary:

The bond is currently \$708,537 and is good through November 11, 2012. The Permittee paid the annual fees on July 13. 2009.

In the last inspection report, the inspector was concerned about trash along the drainage and in the sediment pond. The Permittee cleaned up the trash

Conclusions and Recommendations:

The mine is currently idle although some stockpiled material is or will be shipped to the mill. The Division will monitor the site to insure that all environmental requirements are met.

Inspector's Signature Wand White St 191/2009

cc: Christy Woodward, Denison buzz_rakow@blm.gov wstokes@utah.gov

O:\M017-Garfield\M0170049-TonyM\Inspections\insp-05062009.doc